



Metallurgical Group-Picture 14 Cleaning the Fracture Faces of the Ruptured Section of pipe (piece B) at the NTSB Ashburn, Virginia Facility.