



Metallurgical Group-Picture 19 Ruptured pipe piece showing areas where samples have been cut at the NTSB Ashburn, Virginia Facility