



Metallurgical Group-Picture 20 Sample containing the rupture removed from the ruptured pipe piece at the NTSB Ashburn, Virginia Facility.