

Figure 2b. Exterior surface of the spike tooth area on the landing light surround structure. The brackets indicate the extent of the rubbing damage area. (5X)

Metallurgist's Factual Report No. 97-85