

Figure 3. SEM photograph of the surface of a spike tooth fracture area on the landing light surround structure. (87.9X)




Figure 4. Higher magnification SEM photograph of the mud-cracked oxides on the surface of the spike tooth fracture area on the landing light surround structure. (786X)

Metallurgist's Factual Report No. 97-85