
мW 49 (01/01/07) Бaily track inspection report



Date of Inspection

1-28-2015

Inspector will provide and sign report in duplicate each day and send to Track Supervisor. Track Supervisor will forward one copy of report to Director Track & Structures within 10 days after end of month, indicating thereon corrective action taken in addition to that by inspector on day of inspection. If more space is required to make a complete report, use an additional form.

TO N	ame of Track Supervisor		Line HAVI	en		Subdivision 5
		On the above date	I inspected the fo	llowing trac	ks	
Line	Tracks	From MP	To MP	Walked	Hirail	Inspected from Track #
Harlen	1,2	24.5	523		/	1
L	3	36.9	37.5		/	1
u	1,2	52.3	53.2			2
The following	FRA defects (Part o	ne of MW4) were found	(indicate exact locati	on and measu	rements	of defect) I took the
<u>3</u>	-4	NO FrA	Defects ,	Found	. 	
. (
		سانده سد و همست و آن به به همای این و به و این و به و این و به و این و به و این و این و این و این و این و این و	and the second s			
		<u> </u>	<u> </u>	<u> </u>		
<u> </u>						
			No.		·	
		**************************************	Transport			
				<u> </u>	<u> </u>	
		and the second s	<u> </u>			
		the state of the s	A CONTRACTOR OF THE PROPERTY O			
		and the feature of the second state of the second 	<u> </u>	<u> </u>		
	ranga di arti di	anthire, and a second a second and a second a second and a second and a second and a second and a second and		•		
					•	The state of the s
	<u>ب بنیان نیسته بازی بازی این بازی بازی بازی بازی بازی بازی بازی بازی</u>	anna ann an a	<u> </u>	 		

I also noted other conditions
Surface C 152 TK142 Needs Surpacing
Surface C 152 TK 142 Needs Surfacing TK# 1 mp 29.5- Bridge Approved To be surfaced
Gauge
Welding 4130 120 SW Frog PT + Wing Needs Welding- \$136 218 SW
Insulated joints TK1-M29.3, 34.5, 37.5, 413725, 40.6, 42.8, 44.8, 46.4, 48.4, 51.0 Minping TK2 M24.5, 4136.2N, 40.6, 46.4, 48.4, 29.4
Frogs & switches
Drainage TK # 1 mp 24.5-24.8, 28.4-28.8 Needs Detching - LAKEVICU DR. TK # 2 Green LN, mp 25.8, LAKEVIEW DR NEEDS DETChing
CWR Joints * TK#1 mp 32.1 Needs Tamping
If joint defect is noted it must be identified and a weekly documented follow up inspection is required until remedial action has been taken
ther TK2 MP 42.F. 43.0 Needs STONE ON Shoulder Multiple Locations 1 MP 32.0-34.5, 35.1-35.7 Needs stone on shoulder Multiple Locations 1 MP 35.1 Needs Bridge Timbers 1 143 Needs Ties between 124+21Bow, C\$130 Needs Ties between 124+211. 1 142 MP 46.2 Needs Bridge Timbers, MP 45.0 TK1 Ice in Ruch co
gnature of Supervisor Signature of Inspector (If two Inspectors both signatures required)