



Motor Carrier Photos 1 - 11

Oxnard, California

HWY15MH006

(7 pages)



Photo 1 – This photo depicts compliance help aids maintained in the safety department by the motor carrier.



Photo 2 – This photo depicts an exemplar vehicle of the accident vehicle involved in this crash. This photo shows an identical F450 Ford Pickup truck owned by Harvest Management. This truck represents the same make, model, year and configuration as the accident vehicle.



Photo 3 – This photo depicts some of the buses owned and operated by the carrier. These buses transport farm workers during the harvest season.



Photo 4- This photo depicts some of the various power units owned and operated by the carrier.



Photo 5 –This photo depicts an example of the farm equipment operated by the carrier.



Photo 6 – This type of truck is used in the farming operation by the carrier.



Photo 7 – This photo depicts an example of how the farm equipment is transported in interstate commerce from one farm project to the next.



Photo 8 – This photo depicts a water truck owned and operated by the motor carrier. Local law requires the carrier to spray water on the roads to maintain the dust created by farm traffic.



Photo 9 – This photo depicts the 24 hour maintenance shop operated by The Grower’s Company



Photo 10 – This photo depicts The Grower’s on-site NAPA Dealer auto parts shop.

|

* HARVEST MANAGEMENT *												2-28-15	
SUPERVISOR	FOREMAN	CREW #	BUS - TOILET	MACH #	LOCATION - RANCH	SUPERVISOR	FOREMAN	CREW #	BUS - TOILET	MACH #	LOCATION - RANCH		
WRAP	JORGE S.	1227	53-61	HL125	VUKO 2	CAULIF.							
JAINIE	TINA	1223	52-62	HL126	" "	PANCHO	BERNARDO	1271	6-40	HL112		OUT	
	ROSARIO	1226	51-92	HL124	" "	ALBERTO	MARTIN	1221	14-113	HL114		243	
	RUTH	1269	72-99	HL128	" "		RAMIRO	1237	50-111	HL113		14FG	
RENE	ALBERTO	1211	100-101	HL130	VUKO 2		VERONICA	1286	73-109	HL110		BAN	
	GALDINO	1214	5-90	HL127	" "	BROCCOLU	ESTEBAN	1217	70-108	HB155		BUCHAN	
	MOISES	1231	98-104	HL131	" "		JESUS	1204	3-118			OUT	
	FELIPE	1210	101-91	HL129	VUKO 2		RUBEN	1264	71-117			" "	
JESUS	MANUEL	1213	2-37	HR102	Thacker		LORENA	1254	43-69	HL151		RC	
	MARIO	1215	41-58	HL123	" "		ALICIA	1245	29-100	HB156		HART	
ROM.HRT	ESTHER	1219	97-106	HR109	POTTER								

Photo 11- This photo depicts a wipe off board demonstrating the carrier had a systematic method of repairs and services as required under §396.3.