

## Monville Timothy

---

**From:** McAtee Nancy  
**Sent:** Friday, October 16, 2015 12:04 PM  
**To:** Monville Timothy  
**Subject:** ERA15FA221 email report-Annunciator panel (revised)

Tim,

The annunciator panel from the accident aircraft was radiographed to determine the status and condition of the lightbulb filaments inside. All of the filaments for all of the annunciator bulbs were intact. There was no evidence of stretching found on any of the filaments. A layout diagram of the annunciator panel is shown below. If you have any questions, please feel free to contact me.

Top

<b>Gen Fail</b>
<b>Min Oil Press</b>
<b>Beta</b>
<b>Aft Chip</b>
<b>Fwd Chip</b>
<b>ITT</b>
<b>Status</b>
<b>EHT</b>
<b>Isol Valve</b>
<b>Spare</b>

Nancy B. McAtee

Chemist  
RE-30