



VEHICLE FACTORS GROUP CHAIRMAN'S FACTUAL REPORT

NTSB Vehicle Photos

Biloxi, Mississippi

HWY17MH010

(7 pages)



Vehicle Photo #1 – Overall view of the damage to the left side of the Van Hool Motorcoach during inspection at the Biloxi, Mississippi Police Department Impound Yard.



Vehicle Photo #2 – View of the damage to the left side of the Van Hool Motorcoach.



Vehicle Photo #3 – View of the damage to the right side of the Van Hool Motorcoach from the right front corner.



Vehicle Photo 4 – View of the contact damage to the right rear of the Van Hool Motorcoach. Photo shows damage to the right rear taillight and to the side of the motorcoach above the rear axle.



Vehicle Photo #5 – View of the damaged and flat right steer axle tire of the Van Hool Motorcoach.



Vehicle Photo #6 – View of the damaged interior floorboard of the Van Hool Motorcoach. The luggage compartment below can be seen through the large crack in the floorboard.