



Photo 1 – Initial point of ground contact and main wreckage (Carbon County Sheriff photo)



Photo 2 – Main wreckage, right side.



Photo 3 – Main wreckage, left side.



Photo 4 – Top view of the engine.



Photo 5 – Propeller exhibiting blade twisting.



Photo 6 – Propeller blade showing chordwise scratches and polishing.



Photo 7 – Propeller blade showing leading edge damage and polishing.