#### NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety Washington, D.C. 20594

February 28, 2007

# Errata 1 to Group Chairman's Factual Report

# **OPERATIONS**

#### **DCA06MA064**

#### A. ACCIDENT

Operator: Comair, Inc. dba Comair Airlines dba Delta Connection

Location: Blue Grass Airport, Lexington, Kentucky

Date: August 27, 2006

Time: 0607 eastern daylight time<sup>1</sup>

Airplane: Bombardier CL-600-2B19 (CRJ-100), Registration Number:

N431CA, Serial # 7472

# **ERRATA** to:

# **Section 1.0 HISTORY OF FLIGHT**

Footnote 4 should be changed to read: The LEX runway lights had 5 steps of intensity with step 1 being the lowest and step 5 being the highest.

# **Section 2.1 Captain Jeffrey Adam Clay**

There was a typo in this section and the date that the captain received his Flight Instructor-Airplane Single Engine-Instruments should be changed from July 22, 1991 to July 22, 1998.

# **ERRATA to:**

<u>Operational Factors Factual Attachment 1 – Interview Summaries</u>, page 46, Captain James Michael Maiato, Jr. interview.

Factual Report 1 DCA06MA064

\_

<sup>&</sup>lt;sup>1</sup> All times are eastern daylight time (edt) based on a 24-hour clock, unless otherwise noted. Actual time of accident is approximate, determined by the Flight Data Recorder (FDR) and Air Traffic Control (ATC) transcripts.

In the third paragraph, after the sentence "He described the F/O's health as good except for his knee", add the sentence: "He described the knee problem and that he thought that the F/O had a tear once before and thought that he re-tore it."

Submitted by David Tew