

Factual Report – Attachment 15

FAA Photos

OPERATIONAL FACTORS

ERA18MA099



Photo 1: FAA photo of interior bench seat.¹

¹ Source: Photos provided by the FAA in response to NTSB request 18-119, and received via email on May 21, 2018. Photos provided by the FAA are not of the accident helicopter.



Photo 2: FAA photo of attach point.



Photo 3: FAA photo of lanyards.



Photo 4: FAA photo of carabiner and tether.



Photo 5: FAA photo of helicopter interior.