



Photo 1. Hole #2B. Cutting without coolant with HSS drill to breakdown. Cutting data see report 9634-0101.