



Photo 11. Hole #26 drilled with standard cutting data with HSS and fine bored. No indications came up to view a tBEA.