



Photo 13. Hole #25 drilled with standard cutting data with HSS, fine bored and honed. BEA shows no indications.