



Photo 15. Hole adjacent to hole #1A drilled with HSS to failure by increased cutting data and without coolant. BEA has been performed.