



Photo 16) View of the Thermal and Impact damaged Tail Rotor Assembly. Photo by NTSB.