



Photo 19: Winshield frame at the initial impact point