



Photo 19. Hole adjacent to hole #1B drilled with HSS to failure by increased cutting data and without coolant. BEA has been performed.