



Photo 22. Hole #57 drilled with increased cutting data with HM to breakdown. The hole has also been fine bored and honed. BEA shows a white-grey indication in the drill breakdown area.