



Photo 22. Crankshaft fracture surface.