



Photo 28. Microstructure of hole #52 showing deformed and overheated material. Mag. 32X.