



Photo 29. A close up of photo 28. Microstructure of hole #52 showing deformed and overheated material to a depth of 0.6 - 0.7 mm (0.024-0.028 inch). Mag 64X.