



Photo 29. No. 2 engine reverser hydraulic actuators and TB/FW fragments