



Photo 3. Cross section of hole #2B quite close to the location of the drill breakdown. Mag. 7-8X.