



Photo 4. Cross section of hole #2B quite close to the location of the drill breakdown showing a surface layer with cracks and a appearance similar to the failed