



Photo 44. Inboard Fracture on Blue Main Rotor Blade. Yellow Main Rotor Blade in Background (Eurocopter Photo)