



Photo 5. Cross section of hole #2B quite close to the location of the drill breakdown showing a surface layer with an appearance similar to the failed JT8-hub. Mag. 128X.