



Photo 6. Cross section of hole #2B quite close to the location of the drill breakdown showing a surface layer with a appearance similar to the failed JT8-hub.