



Photo 6. Wire Strike Mark, Left Main Landing Gear