



Photo 7. Hole #2 drilled with standard cutting data with HSS. The arrows show BEA indications consisting of impressions of chips smeared on the hole surface.