



Photo 8. Interior view of left fuselage penetration damage adjacent to row 37.