



Photo 9. Interior view of left fuselage penetration damage adjacent to row 37.