



Photo 9. Longitudinal section of hole 2 through a BEA indication, arrow B in photo 7. A chip with deformed microstructure is smeared into the hole surface. Mag.