



Photo 1 – The photo shows the wreckage path through trees as viewed toward the west.



Photo 2 - Photo of main wreckage along wreckage path as viewed toward the west with engine in view.



Photo 3 - Photo of engine with attached propeller near main wreckage.



Photo 4 - Photo of second engine near main wreckage without propeller attached.



Photo 5 – Photo of second engine's detached propeller that was separated at the propeller hub.