



Photo 1 – Main Wreckage



Photo 2 – Engine and propeller at accident site



Photo 3 – Cut tree branch at accident site



Photo 4 – Engine and propeller after recovery