



Photo 1 – Main Wreckage



Photo 2 – Close Up of Main Wreckage



Photo 3 – Cabin Area



Photo 4 – Nose Landing Gear



Photo 5 – Tree Strikes



Photo 6 – Propeller Strikes



Photo 7 – Engine – Courtesy of Continental Motors



Photo 8 – Propeller – Courtesy of Continental Motors



Photo 9 – Electric Fuel Pump – Courtesy of Textron Aviation



Photo 10 – Fuel Selector Valve



Photo 11 – Forward Cabin Door Upper Frame (Exterior View) – Courtesy of Textron Aviation



Photo 12 - Forward Cabin Door Upper Frame (Interior View) – Courtesy of Textron Aviation



Photo 13 – Interior Door Handle Plate – Courtesy of Textron Aviation



Photo 14 – Interior Door Handle Plate and Rod End – Courtesy of Textron Aviation



Photo 15 – Upper Door Latch After Removal of Door from Wreckage



Photo 16 – Close Up of Upper Door Latch After Removal of Door from Wreckage



Photo 17 – Forward Cabin Door Locking Mechanism Components



Photo 18 - Forward Cabin Door Locking Mechanism Components – Exterior View



Photo 19 – Close Up of Forward End (Bell Crank Behind Interior Handle) of Locking Mechanism



Photo 20 - Close Up of Aft End (Latch and Third Latch Point Bell Crank) – Courtesy of Textron Aviation