



Photo 1 – Main wreckage path and main wreckage at accident site



Photo 2 – Main wreckage at accident site



Photo 3 – Airplane fuselage during examination



Photo 4 – Left engine nacelle during airframe examination



Photo 5 – Right engine nacelle during airframe examination



Photo 6 – Left engine during airframe examination



Photo 7 – Right engine during airframe examination




Photo 8 – Left engine during engine examination




Photo 9 – Left engine crankshaft after removal from engine



Photo 10 – Left engine number 2 connecting rod cap



Photo 11 – Left engine number 2 piston, cylinder and connecting rod