



**Photo 1 – N88452 Bellanca Citabria 7GCBC wreckage**





**Photo 2 - Fractured tree top**





**Photo 3 - Red paint transfer on broken tree section**





**Photo 4 - Front view of airplane at the accident scene**





**Photo 5 - Detailed examination in a hangar**



**Photo 6 - Right wing root damage**





**Photo 7 - Left wing with vortex generators**



**Photo 8 - Lycoming O-320 engine with right side damage**





**Photo 9 - Left side pilot seat leg fractures and modified bracket**