



**Photo 1 – View of main wreckage showing fire damaged fuselage**





**Photo 2 – View of aft section of fuselage showing crush damage**





**Photo 3 – Right side view of cockpit and nose fire damaged**





**Photo 4 – View of left side of fuselage and left engine fire damaged and crushed**





**Photo 5 – Aft view of fuselage**





**Photo 6 – View of a section of the vertical stabilizer and rudder attached to part of the tail section**





**Photo 7 – View of a section of the rudder**





**Photo 8 – View of a right side section of the horizontal stabilizer**





**Photo 9 – View of a left side section of the horizontal stabilizer and damaged elevator sections**





**Photo 10 – View of left wing section damaged**





**Photo 11 – forward view of outboard and inboard section of the left wing**





**Photo 12 - View of inboard section of the right wing**





**Photo 13 – View of outboard section of right wing**





**Photo 14 – View of damaged right engine**





**Photo 15 – View of damaged left engine**





**Photo 16 – View of exemplar aircraft**