



Photo 1 – View of YV1738 (FAA Photo)



Photo 2 – Left Main Wheel Well Structural Damage (FAA Photo)



Photo 3 – Right Main Landing Gear (FAA Photo)



Photo 4 – Left Main Landing Gear (FAA Photo)



Photo 5 – Left Main Landing Gear (FAA Photo)



Photo 6 – Left Main Outboard Tire (FAA Photo)