



Photo 1 – View of Airplane as Found (FAA)



Photo 2 – View of Airplane Prior to Accident. (Owner)



Photo 3 – View of Both Dampeners at the Accident Site (FAA)



Photo 4 – View of Landing Gear Dampeners and Deformed Dampener Mounts after Recovery (FAA)



Photo 5 – View of Fractured Right Main Landing Gear Leg (FAA)