



Photo 1 – View for the airplane from the front



Photo 2 – View of the airplane from the rear



Photo 3 – View of the wreckage taken from the tip of the right wing



Photo 4 – View of the airplane on the 16th T-box with the bay in the background



Photo 5 – View of the propeller at the accident site



Photo 6 – View of the grass at the accident site two days after the accident occurred



Photo 7 – View of the airplane’s tachometer




Photo 8 – View of the back of the engine during the engine exam



Photo 9 – View of one of the wooden propeller blades



Photo 10 – View of the wooden propeller blade that was broken and splintered.