



Photo 1 – View of passengers and first responders near the accident airplane (Jet Center photo)



Photo 2 – View of emergency personnel and first responders at accident site (Jet Center photo)



Photo 3 – View of the accident site from the front of the airplane (Jet Center photo)



Photo 4 – View of the front of the airplane (Jet Center photo)



Photo 5 – View of the ice build-up on the airplane’s windshield (Jet Center photo)



Photo 6 – View of the airplane and damage to the right wing (Jet Center photo)



Photo 7 - View of the damage to the right wing (Jet Center photo)



Photo 8 - View of the damage to the left wing (Jet Center photo)



Photo 9 – View of ice build-up on the AOA probe (Jet Center photo)



Photo 10 – View of runway and the airplane in the grass infield (FAA photo)




Photo 11 – View of the ice build-up on the leading edge of the right wing (FAA photo)



Photo 12 – View of ice build-up on left horizontal stabilizer (FAA photo)



Photo 13 – View of ice build-up of left horizontal and vertical stabilizer (FAA photo)



2018/12/13 14:41

Photo 14 – View of the airplane’s center pedestal (FAA photo)



Photo 15 – View of the airplane’s cabin from the rear (FAA photo)



Photo 16 – View of seat positioned over the toilet (FAA photo)



Photo 17 – View of the couch and cabinet (FAA photo)



Photo 18 – View of couch, cabinet, seats from the front of the cabin (FAA photo)



Photo 19 – View of the couch and its seatbelts (FAA photo)



Photo 20 – View of couch seatbelt with broken steel cable (FAA photo)