



Photo 1 – View of damage to stringers, longerons, and carry through (Courtesy of FAA)