



**Photo 1 – View of damage to the engine mounts (Courtesy of FAA)**