



Photo 1 – View of damage to the airplane’s longerons (Courtesy of Operator)