



**Photo 1 – View of damage to the left wing lift struts (Courtesy of Operator)**