



Photograph # 10 - View of engine after nose gear portion was removed