

Photo 1 – N7208D PA-22 after recovery exhibiting damage to left wing lift strut and left horizontal stabilizer. (Photograph courtesy of airplane owner.)